

Document Nr.: PR3-DARA-RT-0066

Issue: 1.2

Filename: RT-0066_Controller_Board_Irradiation_Test_Report_V1_2.docx

Author: Matthias Gander

Date: 02.02.2018

DARA

Controller Board Irradiation Test Report

FOR PUBLICATION ON ESCIES

	Name	Signature	Date
Prepared by:	Matthias Gander	mga	29.01.2018
Checked by:	Julian Harris, Silvio Koller	jh, sk	02.02.2018
Approved by:	Silvio Koller	sk	02.02.2018

TABLE OF CONTENT

I.	Change Log	3
II.	Abbreviations	3
III.	Applicable Documents	3
IV.	Reference Documents	3

1	Scope / Introduction	4
2	Test summary	4
2.1	CPU and digital circuits	4
2.2	MRAM write/read test	4
2.3	Precision +5V voltage reference	5
2.4	Power supply +12V	5
2.5	Oscillator	5
2.6	Analog digital data acquisition	5
2.7	Zener diodes	5
2.8	Overview of main electronic parts	6
3	Sequence of tests	7
3.1	Commissioning and corrections	7
3.2	Initial electrical test	8
3.3	Irradiation test	8
3.4	Annealing	18
3.5	Accelerate ageing	20
3.6	Repair and final electrical test	21
4	Test build	22
4.1	Electrical setup	22
4.2	Mechanical setup	23

I. Change Log

Please note: Major changes require an x-increase in the format x.1
 Minor changes require an x-increase in the format 1.x
 Draft versions shall be numbered 0.x
 Released versions shall start with 1.x

Issue	Release date	Changes
0.1	23.11.2017	Initial draft version
1.0	16.01.2018	Report completed
1.1	29.01.2018	Added memory W/R test result
1.2	02.02.2018	Report is FOR PUBLICATION ON ESCIES

II. Abbreviations

DARA	Digital Absolute RAdiometer
PMOD	Physikalisch-Meteorologisches Observatorium Davos
RTS	Radiation Test Sample: the DARA Controller Board that was tested

III. Applicable Documents

Some additional documents of RT-0066 can be found in the supplements folder.

Applic. Doc.	Doc. Number	Title	Issue
AD 1	0015-D10-DARA	Irradiation Testplan (Document created by ELSE)	1.2
AD 2	PR3-DARA-TP-0063	Electrical Testplan Controller Board	1.0
AD 3	PR3-DARA-RT-0066	Electrical Test Report before Irradiation Test	1.0
AD 4	PR3-DARA-RT-0066	Electrical Test Zener Diodes	1.0
AD 5	PR3-DARA-RT-0066	Radiation Test Monitor	1.2
AD 6	PR3-DARA-RT-0066	Electrical Test Report after Repair	1.0
AD 7	RA0002657	Radiation Summary DARA RTS (Document created by ESTEC)	1.0
AD 8	PR3-DARA-RT-0066	Measurements and graphs collection	1.0

IV. Reference Documents

Ref. Doc.	Doc. Number	Title	Issue
RD 1	0001-D1-DARA	Declared Component List	1.5
RD 2	0017-D29-DARA	Controller Board Assembly Plan	1.3
RD 3	---	RTS Controller Board Fabrication Log	1.1

Document Nr.: PR3-DARA-RT-0066

Issue: 1.2

Filename: RT-0066_Controller_Board_Irradiation_Test_Report_V1_2.docx

Author: Matthias Gander

Date: 02.02.2018

1 Scope / Introduction

This document outlines the results of the irradiation tests done with the DARA Controller Board RTS. This is the main document which provides the summary of the results. There are several other supplement reports and documents.

2 Test summary

2.1 CPU and digital circuits

Irradiation

The +5V supply started increasing at ~ 7.5 krad. The CPU failed at an irradiation dose of ~ 14.6 krad.

The +5V current consumption was drifting while irradiation, from 136 mA to 450 mA in maximum.

Since the CPU failed and the control bus signals were corrupted, the +3.3 V power consumption of the MRAM increased as well. At some point the +3.3 V voltage supply had to be switched off manually, because the current reached critical high value.

Annealing

The CPU did not recover while annealing.

The +5V current consumption slightly decreased while annealing.

The +3.3 current was still way to high and stable.

Ageing

The CPU still failed after ageing.

The +5V current consumption was slightly decreased after ageing.

The +3.3 current was still way to high and stable.

Repair

When the CPU was replaced, the digital circuits worked properly again. The current consumption of the +5V and +3.3V supply were back in limits.

2.2 MRAM write/read test

Irradiation

A file was stored/written to the MRAM. Then the file had been read back and checked, if still the same content is in it.

This test was performed manually while irradiation several times. The test always passed.

Ageing

After the ageing procedure the write/read test still passed.

2.3 Precision +5V voltage reference

Irradiation

The voltage reference started drifting at ~ 1.9 krad. During the irradiation there was a continuous drifting, at the end of the test the reference voltage reached 5.009 V at a dose of 40.1 krad.

Annealing

While annealing there was first a slightly increase of the reference voltage to 5.010 V, followed by a decrease to 5.008 V.

Ageing

After ageing the reference reached 5.007 V. From this point on, there was no more drifting, the reference voltage is stable at 5.007 V.

2.4 Power supply +12V

Irradiation

The current consumption of the +12V power supply was drifting over irradiation test from originally 8 mA to 34 mA. The drifting started at 16.7 krad.

Annealing

Over the annealing the current consumption decreased from 34 mA to 23 mA.

Ageing

After ageing, the consumption was between 7 mA to 8 mA and stable.

It's not known, if the current consumption of one of the OpAmps or/and the Voltage Reference drifted.

2.5 Oscillator

The Oscillator was properly working over the irradiation tests. The pulse counter had miscounts, before during and after the irradiation test in the same way.

See the Measurements and graphs collection [AD 8].

2.6 Analog digital data acquisition

The housekeeping signals (GND, VCC, and thermistor levels) were only available when the CPU was working. The measurements during beginning of the irradiation and after the repair were alright.

See the Measurements and graphs collection [AD 8].

2.7 Zener diodes

The diodes were disassembled, and the Zener voltage was measured, before and after the irradiation.

The test passed, no significant change of the Zener voltage caused by the irradiation. The Zener voltage increased slightly, 0.6 mV in minimum and 1.6 mV in maximum of the 10 tested diodes.

See report Electrical Test Zener Diodes [AD 4].

2.8 Overview of main electronic parts

The table below shows the main parts of the DARA Controller Board RTS and the test results. For complete part list, see Declared Component List [RD 1].

Part functionality	Name	Part Number	Test result
CPU (central processing unit)	TS68332	5962-9150102MXA	Failed at ~14.6 krad
Watchdog	ISL705CRHVF	5962R1121303VXC	Endured 40.1 krad
Oscillator	QT3005CX-18.432MHz	QT3005CX-18.432MHz	Endured 40.1 krad
MRAM (magneto resistive random-access memory)	EV2A16AMNYU35	EV2A16AMNYU35	Endured 40.1 krad
SRAM (Static random-access memory)	WS512K32N	5962-9461105HTA	Endured 40.1 krad
Level shifter (3.3V <-> 5V logic)	RHRAC164245K01V	5962R9858008VYC	Endured 40.1 krad
Decoder (4 to 16 lines)	M54HC154KG	9205/023/01F	Endured 40.1 krad
Logic components	Several parts, see Declared Component List [RD 1]		Endured 40.1 krad
Voltage reference	REF02AZQMLR	5962R8551401VPA	Started drifting (failed) at ~1.9 krad
ADC (analog digital converter)	ADC128S102WGRQV	5962R0722701VZA	Endured 40.1 krad
Analog multiplexer	ADG725	ADG725	Endured 40.1 krad
OpAmps (operational amplifier)	ISL70419SEHVF	5962F1422601VXC	Endured 40.1 krad
	LM124AWRLQMLV	5962R9950402VDA	Endured 40.1 krad
RS-422 receiver	HS-26C32RH-8	5962F9568901QXC	Endured 40.1 krad
RS-422 driver	HS-26C31RH-8	5962F9666301QXC	Endured 40.1 krad

Document Nr.: PR3-DARA-RT-0066
 Issue: 1.2
 Filename: RT-0066_Controller_Board_Irradiation_Test_Report_V1_2.docx
 Author: Matthias Gander
 Date: 02.02.2018

3 Sequence of tests

This section shows all the test steps and events in chronological order.
 The order of tests was given by the Irradiation Testplan [AD 1].

3.1 Commissioning and corrections

Number	Title	Description	Document reference
1	Board assembling	The Controller Board RTS was assembled according the Declared Component List and assembling plan.	Declared Component List [RD 1] Assembling Plan [RD 2]
2	Design changes and completion of assembling	Some of the latest design changes have been done by PMOD/WRC, and some parts were assembled at PMOD/WRC too.	RTS Fabrication Log [RD 3]
3	Board commissioning, corrections and inspection of board.	Commissioning was done by PMOD/WRC. Some corrections were done because of assembling mistakes and defect of a circuit. A final inspection was done, no defects on the board left.	RTS Fabrication Log [RD 3]

3.2 Initial electrical test

Before the irradiation test, electrical tests were done with the RTS by PMOD/WRC.


Number	Title	Description	Document reference
1	Standard electrical test	The RTS was tested according the standard test plan for DARA Controller Board. The tests passed, no defects or fail functions were known.	Electrical Testplan Controller Board [AD 2] Electrical Test Report before Irradiation Test [AD 3]
2	Zener diodes measurements	The diodes were disassembled, and the Zener voltage was measured. All diodes were working properly, and Zener voltage was in limits.	Electrical Test Zener Diodes [AD 4]

3.3 Irradiation test




The irradiation tests were done at ESTEC, accompanied and supervised by ELSE and PMOD/WRC.

The original measurements and graphs can be found at the Measurements and graphs collection [AD 8].




The following graphs show the drift of the digital power supplies over the irradiation test. If there is a peak going to zero, this means, the supply was switched off temporarily.



The following graphs show the drift of the analog power supplies over the irradiation test. If there is a peak going to zero, this means, the supply was switched off temporarily.



The following graphs show the drift of the reference voltage over the irradiation test. If there is a peak going to zero, this means, the supply was switched off temporarily. The RTS on-board temperatures are as well showed, until the CPU failed, and no more housekeeping data was available.



■ housekeeping/acquisition/CPU_MRAM_TEMP:L1 ■ housekeeping/acquisition/CPU_SRAM_TEMP:L1 ■ housekeeping/acquisition/CPU_OSC_TEMP:L1 ■ housekeeping/acquisition/CPU_ADC_TEMP:L1 ■ housekeeping/acquisition/CPU_CPU_TEMP:L1

Following the overview of the most important events while irradiation test:

Number	Test state	Description	Document reference																																	
1	Pre-run	<p>Pre-run before irradiation was active, RTS is installed in test chamber. All values are in limits:</p> <table border="1"> <thead> <tr> <th>Signal</th> <th>Measured value</th> <th>State</th> </tr> </thead> <tbody> <tr> <td>Radiation dose</td> <td>0.0 krad</td> <td>OK</td> </tr> <tr> <td>Running time</td> <td>1.0 h</td> <td>OK</td> </tr> <tr> <td>CPU</td> <td>Running</td> <td>OK</td> </tr> <tr> <td>Supply +3V3</td> <td>33 mA</td> <td>OK</td> </tr> <tr> <td>Supply +5V</td> <td>136 mA</td> <td>OK</td> </tr> <tr> <td>Supply -12V</td> <td>-2 mA</td> <td>OK</td> </tr> <tr> <td>Supply +12V</td> <td>7 mA</td> <td>OK</td> </tr> <tr> <td>HK VREF</td> <td>5.000 V</td> <td>OK</td> </tr> <tr> <td>ADC CLK</td> <td>9.219 MHz</td> <td>OK</td> </tr> <tr> <td>Log number</td> <td>61</td> <td>OK</td> </tr> </tbody> </table>	Signal	Measured value	State	Radiation dose	0.0 krad	OK	Running time	1.0 h	OK	CPU	Running	OK	Supply +3V3	33 mA	OK	Supply +5V	136 mA	OK	Supply -12V	-2 mA	OK	Supply +12V	7 mA	OK	HK VREF	5.000 V	OK	ADC CLK	9.219 MHz	OK	Log number	61	OK	Radiation Test Monitor [AD 5]
Signal	Measured value	State																																		
Radiation dose	0.0 krad	OK																																		
Running time	1.0 h	OK																																		
CPU	Running	OK																																		
Supply +3V3	33 mA	OK																																		
Supply +5V	136 mA	OK																																		
Supply -12V	-2 mA	OK																																		
Supply +12V	7 mA	OK																																		
HK VREF	5.000 V	OK																																		
ADC CLK	9.219 MHz	OK																																		
Log number	61	OK																																		
2	Run, irradiation active	<p>Irradiation started, all values are in limits. Started: 10.11.2017 at 15:10 Finished: 15.11.2017 at 09:48 Total dose: 40.1 krad</p> <table border="1"> <thead> <tr> <th>Signal</th> <th>Measured value</th> <th>State</th> </tr> </thead> <tbody> <tr> <td>Radiation dose</td> <td>~0.0 krad</td> <td>OK</td> </tr> <tr> <td>Running time</td> <td>2.1 h</td> <td>OK</td> </tr> <tr> <td>CPU</td> <td>Running</td> <td>OK</td> </tr> <tr> <td>Supply +3V3</td> <td>33 mA</td> <td>OK</td> </tr> <tr> <td>Supply +5V</td> <td>136 mA</td> <td>OK</td> </tr> <tr> <td>Supply -12V</td> <td>-2 mA</td> <td>OK</td> </tr> <tr> <td>Supply +12V</td> <td>7 mA</td> <td>OK</td> </tr> <tr> <td>HK VREF</td> <td>5.000 V</td> <td>OK</td> </tr> <tr> <td>ADC CLK</td> <td>9.219 MHz</td> <td>OK</td> </tr> <tr> <td>Log number</td> <td>127</td> <td>OK</td> </tr> </tbody> </table>	Signal	Measured value	State	Radiation dose	~0.0 krad	OK	Running time	2.1 h	OK	CPU	Running	OK	Supply +3V3	33 mA	OK	Supply +5V	136 mA	OK	Supply -12V	-2 mA	OK	Supply +12V	7 mA	OK	HK VREF	5.000 V	OK	ADC CLK	9.219 MHz	OK	Log number	127	OK	Radiation Summary DARA RTS [AD 7]
Signal	Measured value	State																																		
Radiation dose	~0.0 krad	OK																																		
Running time	2.1 h	OK																																		
CPU	Running	OK																																		
Supply +3V3	33 mA	OK																																		
Supply +5V	136 mA	OK																																		
Supply -12V	-2 mA	OK																																		
Supply +12V	7 mA	OK																																		
HK VREF	5.000 V	OK																																		
ADC CLK	9.219 MHz	OK																																		
Log number	127	OK																																		

3	Run, irradiation active	<p>The reference voltage HK VREF begins to drift.</p> <table border="1" data-bbox="483 400 1523 703"> <thead> <tr> <th>Signal</th> <th>Measured value</th> <th>State</th> </tr> </thead> <tbody> <tr> <td>Radiation dose</td> <td>~1.9 krad</td> <td>OK</td> </tr> <tr> <td>Running time</td> <td>7.2 h</td> <td>OK</td> </tr> <tr> <td>CPU</td> <td>Running</td> <td>OK</td> </tr> <tr> <td>Supply +3V3</td> <td>33 mA</td> <td>OK</td> </tr> <tr> <td>Supply +5V</td> <td>136 mA</td> <td>OK</td> </tr> <tr> <td>Supply -12V</td> <td>-2 mA</td> <td>OK</td> </tr> <tr> <td>Supply +12V</td> <td>7 mA</td> <td>OK</td> </tr> <tr> <td>HK VREF</td> <td>5.001</td> <td>Begin of drifting</td> </tr> <tr> <td>ADC CLK</td> <td>9.216 MHz</td> <td>OK</td> </tr> <tr> <td>Log number</td> <td>434</td> <td>OK</td> </tr> </tbody> </table>	Signal	Measured value	State	Radiation dose	~1.9 krad	OK	Running time	7.2 h	OK	CPU	Running	OK	Supply +3V3	33 mA	OK	Supply +5V	136 mA	OK	Supply -12V	-2 mA	OK	Supply +12V	7 mA	OK	HK VREF	5.001	Begin of drifting	ADC CLK	9.216 MHz	OK	Log number	434	OK	
Signal	Measured value	State																																		
Radiation dose	~1.9 krad	OK																																		
Running time	7.2 h	OK																																		
CPU	Running	OK																																		
Supply +3V3	33 mA	OK																																		
Supply +5V	136 mA	OK																																		
Supply -12V	-2 mA	OK																																		
Supply +12V	7 mA	OK																																		
HK VREF	5.001	Begin of drifting																																		
ADC CLK	9.216 MHz	OK																																		
Log number	434	OK																																		
4	Run, irradiation active	<p>The +5V current consumption begins to drift. The temperature of the CPU (highest curve on the previous temperature graph) begins as well to increase.</p> <table border="1" data-bbox="483 858 1523 1161"> <thead> <tr> <th>Signal</th> <th>Measured value</th> <th>State</th> </tr> </thead> <tbody> <tr> <td>Radiation dose</td> <td>~7.5 krad</td> <td>OK</td> </tr> <tr> <td>Running time</td> <td>22.2 h</td> <td>OK</td> </tr> <tr> <td>CPU</td> <td>Running</td> <td>OK</td> </tr> <tr> <td>Supply +3V3</td> <td>33 mA</td> <td>OK</td> </tr> <tr> <td>Supply +5V</td> <td>138 mA</td> <td>Begin of drifting</td> </tr> <tr> <td>Supply -12V</td> <td>-2 mA</td> <td>OK</td> </tr> <tr> <td>Supply +12V</td> <td>7 mA</td> <td>OK</td> </tr> <tr> <td>HK VREF</td> <td>5.002</td> <td>Further drifting</td> </tr> <tr> <td>ADC CLK</td> <td>9.214 MHz</td> <td>OK</td> </tr> <tr> <td>Log number</td> <td>1335</td> <td>OK</td> </tr> </tbody> </table>	Signal	Measured value	State	Radiation dose	~7.5 krad	OK	Running time	22.2 h	OK	CPU	Running	OK	Supply +3V3	33 mA	OK	Supply +5V	138 mA	Begin of drifting	Supply -12V	-2 mA	OK	Supply +12V	7 mA	OK	HK VREF	5.002	Further drifting	ADC CLK	9.214 MHz	OK	Log number	1335	OK	
Signal	Measured value	State																																		
Radiation dose	~7.5 krad	OK																																		
Running time	22.2 h	OK																																		
CPU	Running	OK																																		
Supply +3V3	33 mA	OK																																		
Supply +5V	138 mA	Begin of drifting																																		
Supply -12V	-2 mA	OK																																		
Supply +12V	7 mA	OK																																		
HK VREF	5.002	Further drifting																																		
ADC CLK	9.214 MHz	OK																																		
Log number	1335	OK																																		

5	Run, irradiation active	<p>CPU is no longer running. The CPU housing temperature raised from ~ 29.0 °C, the stabilized temperature after irradiation test was started, to ~ 36.5 °C, when the CPU failed. The increase of temperature correlated with the increase of the +5V current consumption, which is the power supply of the CPU.</p> <table border="1" data-bbox="488 499 1525 831"> <thead> <tr> <th>Signal</th> <th>Measured value</th> <th>State</th> </tr> </thead> <tbody> <tr> <td>Radiation dose</td> <td>~ 14.6 krad</td> <td>OK</td> </tr> <tr> <td>Running time</td> <td>41.5 h</td> <td>OK</td> </tr> <tr> <td>CPU</td> <td>Failure</td> <td>No more communication with EGSE</td> </tr> <tr> <td>Supply +3V3</td> <td>33 mA</td> <td>OK</td> </tr> <tr> <td>Supply +5V</td> <td>231 mA</td> <td>Further drifting</td> </tr> <tr> <td>Supply -12V</td> <td>-0.2 mA</td> <td>OK</td> </tr> <tr> <td>Supply +12V</td> <td>8 mA</td> <td>OK, increased from 7 mA to 8 mA, but stable then for long time.</td> </tr> <tr> <td>HK VREF</td> <td>5.004</td> <td>Further drifting</td> </tr> <tr> <td>ADC CLK</td> <td>9.216 MHz</td> <td>OK</td> </tr> <tr> <td>Log number</td> <td>2491</td> <td>OK</td> </tr> </tbody> </table>	Signal	Measured value	State	Radiation dose	~ 14.6 krad	OK	Running time	41.5 h	OK	CPU	Failure	No more communication with EGSE	Supply +3V3	33 mA	OK	Supply +5V	231 mA	Further drifting	Supply -12V	-0.2 mA	OK	Supply +12V	8 mA	OK, increased from 7 mA to 8 mA, but stable then for long time.	HK VREF	5.004	Further drifting	ADC CLK	9.216 MHz	OK	Log number	2491	OK	
Signal	Measured value	State																																		
Radiation dose	~ 14.6 krad	OK																																		
Running time	41.5 h	OK																																		
CPU	Failure	No more communication with EGSE																																		
Supply +3V3	33 mA	OK																																		
Supply +5V	231 mA	Further drifting																																		
Supply -12V	-0.2 mA	OK																																		
Supply +12V	8 mA	OK, increased from 7 mA to 8 mA, but stable then for long time.																																		
HK VREF	5.004	Further drifting																																		
ADC CLK	9.216 MHz	OK																																		
Log number	2491	OK																																		
6	Run, irradiation active	<p>Supply +5V and +3V3 current consumptions have changes up and down.</p> <table border="1" data-bbox="488 959 1525 1265"> <thead> <tr> <th>Signal</th> <th>Measured value</th> <th>State</th> </tr> </thead> <tbody> <tr> <td>Radiation dose</td> <td>~ 16.2 krad</td> <td>OK</td> </tr> <tr> <td>Running time</td> <td>45.9 h</td> <td>OK</td> </tr> <tr> <td>CPU</td> <td>Failure</td> <td>NOK</td> </tr> <tr> <td>Supply +3V3</td> <td>18 mA</td> <td>Changes up and down for longer time</td> </tr> <tr> <td>Supply +5V</td> <td>201 mA</td> <td>Changes up and down for longer time</td> </tr> <tr> <td>Supply -12V</td> <td>-0.2 mA</td> <td>OK</td> </tr> <tr> <td>Supply +12V</td> <td>8 mA</td> <td>OK</td> </tr> <tr> <td>HK VREF</td> <td>5.004</td> <td>Drifting in general</td> </tr> <tr> <td>ADC CLK</td> <td>9.218 MHz</td> <td>OK</td> </tr> <tr> <td>Log number</td> <td>2757</td> <td>OK</td> </tr> </tbody> </table>	Signal	Measured value	State	Radiation dose	~ 16.2 krad	OK	Running time	45.9 h	OK	CPU	Failure	NOK	Supply +3V3	18 mA	Changes up and down for longer time	Supply +5V	201 mA	Changes up and down for longer time	Supply -12V	-0.2 mA	OK	Supply +12V	8 mA	OK	HK VREF	5.004	Drifting in general	ADC CLK	9.218 MHz	OK	Log number	2757	OK	
Signal	Measured value	State																																		
Radiation dose	~ 16.2 krad	OK																																		
Running time	45.9 h	OK																																		
CPU	Failure	NOK																																		
Supply +3V3	18 mA	Changes up and down for longer time																																		
Supply +5V	201 mA	Changes up and down for longer time																																		
Supply -12V	-0.2 mA	OK																																		
Supply +12V	8 mA	OK																																		
HK VREF	5.004	Drifting in general																																		
ADC CLK	9.218 MHz	OK																																		
Log number	2757	OK																																		

7	Run, irradiation active	<p>Supply +12V current started increasing.</p> <table border="1" data-bbox="483 434 1520 764"> <thead> <tr> <th>Signal</th> <th>Measured value</th> <th>State</th> </tr> </thead> <tbody> <tr> <td>Radiation dose</td> <td>~16.7 krad</td> <td>OK</td> </tr> <tr> <td>Running time</td> <td>47.2 h</td> <td>OK</td> </tr> <tr> <td>CPU</td> <td>Failure</td> <td>NOK</td> </tr> <tr> <td>Supply +3V3</td> <td>18 mA</td> <td>Changes up and down for longer time</td> </tr> <tr> <td>Supply +5V</td> <td>213 mA</td> <td>Changes up and down for longer time, the starting to increase drastically</td> </tr> <tr> <td>Supply-12V</td> <td>-2 mA</td> <td>OK</td> </tr> <tr> <td>Supply +12V</td> <td>9 mA</td> <td>Begin of drifting</td> </tr> <tr> <td>HK VREF</td> <td>5.004 V</td> <td>Drifting in general</td> </tr> <tr> <td>ADC CLK</td> <td>9.219 MHz</td> <td>OK, sometimes a miscount probably</td> </tr> <tr> <td>Log number</td> <td>2832</td> <td>OK</td> </tr> </tbody> </table>	Signal	Measured value	State	Radiation dose	~16.7 krad	OK	Running time	47.2 h	OK	CPU	Failure	NOK	Supply +3V3	18 mA	Changes up and down for longer time	Supply +5V	213 mA	Changes up and down for longer time, the starting to increase drastically	Supply-12V	-2 mA	OK	Supply +12V	9 mA	Begin of drifting	HK VREF	5.004 V	Drifting in general	ADC CLK	9.219 MHz	OK, sometimes a miscount probably	Log number	2832	OK	
Signal	Measured value	State																																		
Radiation dose	~16.7 krad	OK																																		
Running time	47.2 h	OK																																		
CPU	Failure	NOK																																		
Supply +3V3	18 mA	Changes up and down for longer time																																		
Supply +5V	213 mA	Changes up and down for longer time, the starting to increase drastically																																		
Supply-12V	-2 mA	OK																																		
Supply +12V	9 mA	Begin of drifting																																		
HK VREF	5.004 V	Drifting in general																																		
ADC CLK	9.219 MHz	OK, sometimes a miscount probably																																		
Log number	2832	OK																																		
8	Run, irradiation paused	<p>Supply +3V3 and 5V current increased drastically. Irradiation was switched off, to see if the RTS may recover. There were attempts made, switching off and on the supplies, to bring the RTS in a better state again, but without success.</p> <table border="1" data-bbox="483 992 1520 1294"> <thead> <tr> <th>Signal</th> <th>Measured value</th> <th>State</th> </tr> </thead> <tbody> <tr> <td>Radiation dose</td> <td>~23.6 krad</td> <td>OK</td> </tr> <tr> <td>Running time</td> <td>66.0 h</td> <td>OK</td> </tr> <tr> <td>CPU</td> <td>Failure</td> <td>NOK</td> </tr> <tr> <td>Supply +3V3</td> <td>124 mA</td> <td>Current consumption highly increased</td> </tr> <tr> <td>Supply +5V</td> <td>346 mA</td> <td>Current consumption highly increased</td> </tr> <tr> <td>Supply-12V</td> <td>-2 mA</td> <td>OK</td> </tr> <tr> <td>Supply +12V</td> <td>14 mA</td> <td>Drifting in general</td> </tr> <tr> <td>HK VREF</td> <td>5.006 V</td> <td>Drifting in general</td> </tr> <tr> <td>ADC CLK</td> <td>9.207 MHz</td> <td>OK, sometimes a miscount probably</td> </tr> <tr> <td>Log number</td> <td>3961</td> <td>OK</td> </tr> </tbody> </table>	Signal	Measured value	State	Radiation dose	~23.6 krad	OK	Running time	66.0 h	OK	CPU	Failure	NOK	Supply +3V3	124 mA	Current consumption highly increased	Supply +5V	346 mA	Current consumption highly increased	Supply-12V	-2 mA	OK	Supply +12V	14 mA	Drifting in general	HK VREF	5.006 V	Drifting in general	ADC CLK	9.207 MHz	OK, sometimes a miscount probably	Log number	3961	OK	
Signal	Measured value	State																																		
Radiation dose	~23.6 krad	OK																																		
Running time	66.0 h	OK																																		
CPU	Failure	NOK																																		
Supply +3V3	124 mA	Current consumption highly increased																																		
Supply +5V	346 mA	Current consumption highly increased																																		
Supply-12V	-2 mA	OK																																		
Supply +12V	14 mA	Drifting in general																																		
HK VREF	5.006 V	Drifting in general																																		
ADC CLK	9.207 MHz	OK, sometimes a miscount probably																																		
Log number	3961	OK																																		

9	Run, irradiation active again	<p>Supply +3V3 and 5V current still very high. The +3V3 supply finally was switched off, because current consumption out of control. Supply +5V was increased to 5.25 V, because of the high voltage drop over the latch up circuit on the RTS. The CPU's supply voltage is high enough, so that there is no brown out reset. Irradiation switched on again.</p> <table border="1" data-bbox="483 600 1525 903"> <thead> <tr> <th>Signal</th> <th>Measured value</th> <th>State</th> </tr> </thead> <tbody> <tr> <td>Radiation dose</td> <td>~23.7 krad</td> <td>OK</td> </tr> <tr> <td>Running time</td> <td>66.9 h</td> <td>OK</td> </tr> <tr> <td>CPU</td> <td>Failure</td> <td>NOK</td> </tr> <tr> <td>Supply +3V3</td> <td>0 mA</td> <td>Switched off</td> </tr> <tr> <td>Supply +5V</td> <td>364 mA</td> <td>Current consumption drastically increased</td> </tr> <tr> <td>Supply -12V</td> <td>-2 mA</td> <td>OK</td> </tr> <tr> <td>Supply +12V</td> <td>14 mA</td> <td>Drifting in general</td> </tr> <tr> <td>HK VREF</td> <td>5.006 V</td> <td>Drifting in general</td> </tr> <tr> <td>ADC CLK</td> <td>9.22 MHz</td> <td>OK</td> </tr> <tr> <td>Log number</td> <td>4013</td> <td>OK</td> </tr> </tbody> </table>	Signal	Measured value	State	Radiation dose	~23.7 krad	OK	Running time	66.9 h	OK	CPU	Failure	NOK	Supply +3V3	0 mA	Switched off	Supply +5V	364 mA	Current consumption drastically increased	Supply -12V	-2 mA	OK	Supply +12V	14 mA	Drifting in general	HK VREF	5.006 V	Drifting in general	ADC CLK	9.22 MHz	OK	Log number	4013	OK	
Signal	Measured value	State																																		
Radiation dose	~23.7 krad	OK																																		
Running time	66.9 h	OK																																		
CPU	Failure	NOK																																		
Supply +3V3	0 mA	Switched off																																		
Supply +5V	364 mA	Current consumption drastically increased																																		
Supply -12V	-2 mA	OK																																		
Supply +12V	14 mA	Drifting in general																																		
HK VREF	5.006 V	Drifting in general																																		
ADC CLK	9.22 MHz	OK																																		
Log number	4013	OK																																		
10	Run, irradiation active	<p>Supply +5V started slightly to decrease, but still very high.</p> <table border="1" data-bbox="483 1062 1525 1366"> <thead> <tr> <th>Signal</th> <th>Measured value</th> <th>State</th> </tr> </thead> <tbody> <tr> <td>Radiation dose</td> <td>~24.0 krad</td> <td>OK</td> </tr> <tr> <td>Running time</td> <td>67.8 h</td> <td>OK</td> </tr> <tr> <td>CPU</td> <td>Failure</td> <td>NOK</td> </tr> <tr> <td>Supply +3V3</td> <td>0 mA</td> <td>Switched off</td> </tr> <tr> <td>Supply +5V</td> <td>362 mA</td> <td>Current consumption to high, but slightly decreasing</td> </tr> <tr> <td>Supply -12V</td> <td>-2 mA</td> <td>OK</td> </tr> <tr> <td>Supply +12V</td> <td>14 mA</td> <td>Drifting in general</td> </tr> <tr> <td>HK VREF</td> <td>5.006 V</td> <td>Drifting in general</td> </tr> <tr> <td>ADC CLK</td> <td>9.208 MHz</td> <td>OK</td> </tr> <tr> <td>Log number</td> <td>4070</td> <td>OK</td> </tr> </tbody> </table>	Signal	Measured value	State	Radiation dose	~24.0 krad	OK	Running time	67.8 h	OK	CPU	Failure	NOK	Supply +3V3	0 mA	Switched off	Supply +5V	362 mA	Current consumption to high, but slightly decreasing	Supply -12V	-2 mA	OK	Supply +12V	14 mA	Drifting in general	HK VREF	5.006 V	Drifting in general	ADC CLK	9.208 MHz	OK	Log number	4070	OK	
Signal	Measured value	State																																		
Radiation dose	~24.0 krad	OK																																		
Running time	67.8 h	OK																																		
CPU	Failure	NOK																																		
Supply +3V3	0 mA	Switched off																																		
Supply +5V	362 mA	Current consumption to high, but slightly decreasing																																		
Supply -12V	-2 mA	OK																																		
Supply +12V	14 mA	Drifting in general																																		
HK VREF	5.006 V	Drifting in general																																		
ADC CLK	9.208 MHz	OK																																		
Log number	4070	OK																																		

11	Measurement to be stopped, irradiation finished	<p>All supplies and irradiation will be switched off.</p> <table border="1" data-bbox="483 467 1523 770"> <thead> <tr> <th>Signal</th> <th>Measured value</th> <th>State</th> </tr> </thead> <tbody> <tr> <td>Radiation dose (total dose)</td> <td>~40.1 krad</td> <td>OK</td> </tr> <tr> <td>Running time</td> <td>112.7 h</td> <td>OK</td> </tr> <tr> <td>CPU</td> <td>Failure</td> <td>NOK</td> </tr> <tr> <td>Supply +3V3</td> <td>0 mA</td> <td>Switched off</td> </tr> <tr> <td>Supply +5V</td> <td>356 mA</td> <td>Current consumption to high, but slightly decreasing</td> </tr> <tr> <td>Supply -12V</td> <td>-2 mA</td> <td>OK</td> </tr> <tr> <td>Supply +12V</td> <td>34 mA</td> <td>Drifting in general</td> </tr> <tr> <td>HK VREF</td> <td>5.009 V</td> <td>Drifting in general</td> </tr> <tr> <td>ADC CLK</td> <td>9.211 MHz</td> <td>OK</td> </tr> <tr> <td>Log number</td> <td>6761</td> <td>OK</td> </tr> </tbody> </table>	Signal	Measured value	State	Radiation dose (total dose)	~40.1 krad	OK	Running time	112.7 h	OK	CPU	Failure	NOK	Supply +3V3	0 mA	Switched off	Supply +5V	356 mA	Current consumption to high, but slightly decreasing	Supply -12V	-2 mA	OK	Supply +12V	34 mA	Drifting in general	HK VREF	5.009 V	Drifting in general	ADC CLK	9.211 MHz	OK	Log number	6761	OK	
Signal	Measured value	State																																		
Radiation dose (total dose)	~40.1 krad	OK																																		
Running time	112.7 h	OK																																		
CPU	Failure	NOK																																		
Supply +3V3	0 mA	Switched off																																		
Supply +5V	356 mA	Current consumption to high, but slightly decreasing																																		
Supply -12V	-2 mA	OK																																		
Supply +12V	34 mA	Drifting in general																																		
HK VREF	5.009 V	Drifting in general																																		
ADC CLK	9.211 MHz	OK																																		
Log number	6761	OK																																		

3.4 Annealing

The annealing was performed at PMOD/WRC.

Number	Title	Description	Document reference																																	
1	Pause after irradiation test	Setup: RTS not biased Duration: ~ 29 h																																		
2	Annealing	Setup: RTS biased, continuous monitoring with Radiation Test Monitor Duration: 168 h (7 days) Started: 16.11.2017 at 14:16 Finished: 23.11.2017 at 14:42 Ambient temperature: 22 °C +/- 3 °C (room temperature)	Irradiation Testplan [AD 1] Radiation Test Monitor [AD 5]																																	
3	Electrical tests	Additional between tests while annealing: no additional effects or failure occurred	Not reported																																	
4	Run, annealing	After a pause after irradiation test, the current of the +3V3 supply was almost nominal value. <table border="1"> <thead> <tr> <th>Signal</th> <th>Measured value</th> <th>State</th> </tr> </thead> <tbody> <tr> <td>Radiation dose (total dose)</td> <td>40.1 krad</td> <td>OK</td> </tr> <tr> <td>Running time</td> <td>112.7 h</td> <td>OK</td> </tr> <tr> <td>CPU</td> <td>Failure</td> <td>NOK</td> </tr> <tr> <td>Supply +3V3</td> <td>36 mA</td> <td>Almost back to nominal value</td> </tr> <tr> <td>Supply +5V</td> <td>355 mA</td> <td>Current consumption to high</td> </tr> <tr> <td>Supply -12V</td> <td>-2 mA</td> <td>OK</td> </tr> <tr> <td>Supply +12V</td> <td>33 mA</td> <td>Value to high</td> </tr> <tr> <td>HK VREF</td> <td>5.010 V</td> <td>Value to high</td> </tr> <tr> <td>ADC CLK</td> <td>9.215 MHz</td> <td>OK</td> </tr> <tr> <td>Log number</td> <td>6764</td> <td>OK</td> </tr> </tbody> </table>	Signal	Measured value	State	Radiation dose (total dose)	40.1 krad	OK	Running time	112.7 h	OK	CPU	Failure	NOK	Supply +3V3	36 mA	Almost back to nominal value	Supply +5V	355 mA	Current consumption to high	Supply -12V	-2 mA	OK	Supply +12V	33 mA	Value to high	HK VREF	5.010 V	Value to high	ADC CLK	9.215 MHz	OK	Log number	6764	OK	
Signal	Measured value	State																																		
Radiation dose (total dose)	40.1 krad	OK																																		
Running time	112.7 h	OK																																		
CPU	Failure	NOK																																		
Supply +3V3	36 mA	Almost back to nominal value																																		
Supply +5V	355 mA	Current consumption to high																																		
Supply -12V	-2 mA	OK																																		
Supply +12V	33 mA	Value to high																																		
HK VREF	5.010 V	Value to high																																		
ADC CLK	9.215 MHz	OK																																		
Log number	6764	OK																																		

5	Run, annealing	<p>After a power off / on, the current from +3V3 supply was again way too high. The reason is probably the invalid control signals from the CPU, the IO's have random levels. Nevertheless the supply +3V3 is still switched on.</p> <table border="1" data-bbox="640 504 1641 807"> <thead> <tr> <th>Signal</th> <th>Measured value</th> <th>State</th> </tr> </thead> <tbody> <tr> <td>Radiation dose (total dose)</td> <td>40.1 krad</td> <td>OK</td> </tr> <tr> <td>Running time</td> <td>137.5 h</td> <td>OK</td> </tr> <tr> <td>CPU</td> <td>Failure</td> <td>NOK</td> </tr> <tr> <td>Supply +3V3</td> <td>121 mA</td> <td>Current consumption again way too high</td> </tr> <tr> <td>Supply +5V</td> <td>345 mA</td> <td>Current consumption to high</td> </tr> <tr> <td>Supply -12V</td> <td>-2 mA</td> <td>OK</td> </tr> <tr> <td>Supply +12V</td> <td>28 mA</td> <td>Value to high, bus started to decrease slightly</td> </tr> <tr> <td>HK VREF</td> <td>5.009 V</td> <td>Value to high, bus started to decrease slightly</td> </tr> <tr> <td>ADC CLK</td> <td>9.213 MHz</td> <td>OK</td> </tr> <tr> <td>Log number</td> <td>8250</td> <td>OK</td> </tr> </tbody> </table>	Signal	Measured value	State	Radiation dose (total dose)	40.1 krad	OK	Running time	137.5 h	OK	CPU	Failure	NOK	Supply +3V3	121 mA	Current consumption again way too high	Supply +5V	345 mA	Current consumption to high	Supply -12V	-2 mA	OK	Supply +12V	28 mA	Value to high, bus started to decrease slightly	HK VREF	5.009 V	Value to high, bus started to decrease slightly	ADC CLK	9.213 MHz	OK	Log number	8250	OK	
Signal	Measured value	State																																		
Radiation dose (total dose)	40.1 krad	OK																																		
Running time	137.5 h	OK																																		
CPU	Failure	NOK																																		
Supply +3V3	121 mA	Current consumption again way too high																																		
Supply +5V	345 mA	Current consumption to high																																		
Supply -12V	-2 mA	OK																																		
Supply +12V	28 mA	Value to high, bus started to decrease slightly																																		
HK VREF	5.009 V	Value to high, bus started to decrease slightly																																		
ADC CLK	9.213 MHz	OK																																		
Log number	8250	OK																																		
6	Measurement stopped, annealing finished	<p>The CPU has not recovered while annealing. Some of the current and voltage values decreased slightly during annealing, but still too high.</p> <table border="1" data-bbox="640 951 1641 1254"> <thead> <tr> <th>Signal</th> <th>Measured value</th> <th>State</th> </tr> </thead> <tbody> <tr> <td>Radiation dose (total dose)</td> <td>40.1 krad</td> <td>OK</td> </tr> <tr> <td>Running time</td> <td>280.5 h</td> <td>OK</td> </tr> <tr> <td>CPU</td> <td>Failure</td> <td>NOK</td> </tr> <tr> <td>Supply +3V3</td> <td>123 mA</td> <td>Value to high, almost stable while annealing</td> </tr> <tr> <td>Supply +5V</td> <td>332 mA</td> <td>Value to high, slightly decreased while annealing</td> </tr> <tr> <td>Supply -12V</td> <td>-2 mA</td> <td>OK</td> </tr> <tr> <td>Supply +12V</td> <td>23 mA</td> <td>Value to high, slightly decreased while annealing</td> </tr> <tr> <td>HK VREF</td> <td>5.008</td> <td>Value to high, slightly decreased while annealing</td> </tr> <tr> <td>ADC CLK</td> <td>9.211 MHz</td> <td>OK</td> </tr> <tr> <td>Log number</td> <td>16831</td> <td>OK</td> </tr> </tbody> </table>	Signal	Measured value	State	Radiation dose (total dose)	40.1 krad	OK	Running time	280.5 h	OK	CPU	Failure	NOK	Supply +3V3	123 mA	Value to high, almost stable while annealing	Supply +5V	332 mA	Value to high, slightly decreased while annealing	Supply -12V	-2 mA	OK	Supply +12V	23 mA	Value to high, slightly decreased while annealing	HK VREF	5.008	Value to high, slightly decreased while annealing	ADC CLK	9.211 MHz	OK	Log number	16831	OK	
Signal	Measured value	State																																		
Radiation dose (total dose)	40.1 krad	OK																																		
Running time	280.5 h	OK																																		
CPU	Failure	NOK																																		
Supply +3V3	123 mA	Value to high, almost stable while annealing																																		
Supply +5V	332 mA	Value to high, slightly decreased while annealing																																		
Supply -12V	-2 mA	OK																																		
Supply +12V	23 mA	Value to high, slightly decreased while annealing																																		
HK VREF	5.008	Value to high, slightly decreased while annealing																																		
ADC CLK	9.211 MHz	OK																																		
Log number	16831	OK																																		

3.5 Accelerate ageing

The ageing was performed at PMOD/WRC.

Number	Title	Description	Document reference																																	
1	Accelerated ageing	Setup: RTS not biased, stored in oven Duration: 168 h (7 days) Started: 23.11.2017 at 14:50 Finished: 30.11.2017 at 14:55 Ambient temperature: 100 °C +/- 3 °C	Irradiation Testplan [AD 1]																																	
2	Run after ageing	The following measurements were done after ageing. <table border="1" data-bbox="638 750 1646 1053"> <thead> <tr> <th>Signal</th> <th>Measured value</th> <th>State</th> </tr> </thead> <tbody> <tr> <td>Radiation dose (total dose)</td> <td>40.1 krad</td> <td>OK</td> </tr> <tr> <td>Running time</td> <td>280.9 h</td> <td>OK</td> </tr> <tr> <td>CPU</td> <td>Failure</td> <td>NOK</td> </tr> <tr> <td>Supply +3V3</td> <td>127 mA</td> <td>Value to high, slightly increased after ageing</td> </tr> <tr> <td>Supply +5V</td> <td>293 mA</td> <td>Current consumption to high, decreased after ageing</td> </tr> <tr> <td>Supply -12V</td> <td>-2 mA</td> <td>OK</td> </tr> <tr> <td>Supply +12V</td> <td>7 mA</td> <td>Back to normal value after ageing</td> </tr> <tr> <td>HK VREF</td> <td>5.007 V</td> <td>Value to high, slightly decreased after ageing</td> </tr> <tr> <td>ADC CLK</td> <td>9.217 MHz</td> <td>OK</td> </tr> <tr> <td>Log number</td> <td>16853</td> <td>OK</td> </tr> </tbody> </table>	Signal	Measured value	State	Radiation dose (total dose)	40.1 krad	OK	Running time	280.9 h	OK	CPU	Failure	NOK	Supply +3V3	127 mA	Value to high, slightly increased after ageing	Supply +5V	293 mA	Current consumption to high, decreased after ageing	Supply -12V	-2 mA	OK	Supply +12V	7 mA	Back to normal value after ageing	HK VREF	5.007 V	Value to high, slightly decreased after ageing	ADC CLK	9.217 MHz	OK	Log number	16853	OK	Radiation Test Monitor [AD 5]
Signal	Measured value	State																																		
Radiation dose (total dose)	40.1 krad	OK																																		
Running time	280.9 h	OK																																		
CPU	Failure	NOK																																		
Supply +3V3	127 mA	Value to high, slightly increased after ageing																																		
Supply +5V	293 mA	Current consumption to high, decreased after ageing																																		
Supply -12V	-2 mA	OK																																		
Supply +12V	7 mA	Back to normal value after ageing																																		
HK VREF	5.007 V	Value to high, slightly decreased after ageing																																		
ADC CLK	9.217 MHz	OK																																		
Log number	16853	OK																																		

3.6 Repair and final electrical test

Since the board was not running anymore after the irradiation test, some repairs were made to evaluate which circuits succeeded.

Number	Title	Description	Document reference																																	
1	Replaced CPU	Damaged CPU was replaced.	RTS Fabrication Log [RD 3]																																	
2	Run after CPU was replaced	<p>After replacing the CPU, the board was working properly. Except the reference voltage was still out of limits:</p> <table border="1"> <thead> <tr> <th>Signal</th> <th>Measured value</th> <th>State</th> </tr> </thead> <tbody> <tr> <td>Radiation dose (total dose)</td> <td>40.1 krad</td> <td>OK</td> </tr> <tr> <td>Running time</td> <td>281.1 h</td> <td>OK</td> </tr> <tr> <td>CPU</td> <td>Running</td> <td>OK</td> </tr> <tr> <td>Supply +3V3</td> <td>33 mA</td> <td>OK (33 mA before irradiation test)</td> </tr> <tr> <td>Supply +5V</td> <td>134 mA</td> <td>OK (136 mA before irradiation test)</td> </tr> <tr> <td>Supply -12V</td> <td>-2 mA</td> <td>OK (-2 mA before irradiation test)</td> </tr> <tr> <td>Supply +12V</td> <td>8 mA</td> <td>OK (-7 mA before irradiation test)</td> </tr> <tr> <td>HK VREF</td> <td>5.007 V</td> <td>NOK</td> </tr> <tr> <td>ADC CLK</td> <td>9.213 MHz</td> <td>OK</td> </tr> <tr> <td>Log number</td> <td>16865</td> <td>OK</td> </tr> </tbody> </table>	Signal	Measured value	State	Radiation dose (total dose)	40.1 krad	OK	Running time	281.1 h	OK	CPU	Running	OK	Supply +3V3	33 mA	OK (33 mA before irradiation test)	Supply +5V	134 mA	OK (136 mA before irradiation test)	Supply -12V	-2 mA	OK (-2 mA before irradiation test)	Supply +12V	8 mA	OK (-7 mA before irradiation test)	HK VREF	5.007 V	NOK	ADC CLK	9.213 MHz	OK	Log number	16865	OK	Radiation Test Monitor [AD 5]
Signal	Measured value	State																																		
Radiation dose (total dose)	40.1 krad	OK																																		
Running time	281.1 h	OK																																		
CPU	Running	OK																																		
Supply +3V3	33 mA	OK (33 mA before irradiation test)																																		
Supply +5V	134 mA	OK (136 mA before irradiation test)																																		
Supply -12V	-2 mA	OK (-2 mA before irradiation test)																																		
Supply +12V	8 mA	OK (-7 mA before irradiation test)																																		
HK VREF	5.007 V	NOK																																		
ADC CLK	9.213 MHz	OK																																		
Log number	16865	OK																																		
3	Standard electrical test	The RTS was tested according the standard test plan for DARA Controller Board. All tests passed, except the voltage reference.	Controller Board Testplan [AD 2] Electrical Test Final [AD 6]																																	
4	Zener diodes measurements	The diodes were disassembled, and the Zener voltage was measured. The test passed, no significant change of the Zener voltage, compared to the measurements before the irradiation tests. The Zener voltage increased slightly, 0.6 mV in minimum and 1.6 mV in maximum of the 10 tested diodes.	Electrical Test Zener Diodes [AD 4] RTS fabrication log [RD 3]																																	

Document Nr.: PR3-DARA-RT-0066

Issue: 1.2

Filename: RT-0066_Controller_Board_Irradiation_Test_Report_V1_2.docx


Author: Matthias Gander

Date: 02.02.2018

4 Test build

4.1 Electrical setup

The following block diagram shows the electrical setup. See Radiation Test Monitor [AD 5] for more details.



Document Nr.: PR3-DARA-RT-0066

Issue: 1.2

Filename: RT-0066_Controller_Board_Irradiation_Test_Report_V1_2.docx

Author: Matthias Gander

Date: 02.02.2018

4.2 Mechanical setup

The following pictures show the mechanical setup in the irradiation test facility. See Radiation Test Monitor [AD 5] and Radiation Summary DARA RTS [AD 7] for more details.

